
Alert number	<u>SR/02526/26</u>
--------------	--------------------



Notifying country	France
-------------------	--------

Product category	Motor vehicles
------------------	----------------

Type	Consumer
------	----------

Product	Motorcycle
---------	------------

Name	S 1000 RR
------	-----------

Brand	BMW Motorrad
-------	--------------

EC-type approval/model	e1*168/2013*00378* e1*168/2013*00091* e1*168/2013*00092* e1*168/2013*00377*
------------------------	--

Production dates	15.01.2019 - 10.07.2026
------------------	-------------------------

Company recall code	0000510200
---------------------	------------

Product description	Motorcycle.
---------------------	-------------

Risk type	Injuries
-----------	----------

Risk description	The vibration level of the motorcycle may cause an internal component of the ignition lock to wear prematurely, leading to sporadic loss of electrical contact. As a result, the ignition may be interrupted either at a standstill or while riding. This could cause the engine to stall and lead to loss of the display cluster, rear light, indicators and electrically powered assistance systems, such as ABS, increasing the risk of an
------------------	---

accident.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply	This product does not comply with the Regulation on the approval and market surveillance of two- or three-wheel vehicles and quadricycles.
---	--

Country of origin	Germany
-------------------	---------

Measures taken by economic operators	Recall of the product from end users Manufacturer
--------------------------------------	--

Date of entry into force	20/08/2026
--------------------------	------------

Products were found and measures were taken also in	Bulgaria Germany Croatia Hungary Ireland Luxembourg Slovenia
---	--