



## Safety Gate: Rapid Alert System for dangerous non-food products

|   |   |
|---|---|
| Alert number  | A12/01105/20  |
| Category  | Motor vehicles  |
| Type of alert                                       | Products with serious risks   |
| Product user  | Consumer  |
| Product   | Passenger car   |
| Brand   | Mercedes-Benz   |
| Name  | C-Class, E-Class, GLC, AMG GT, EQC  |
| Type / number of model                              | Type-approval numbers: e1*2001/116*0457*47-*49, e1*2007/46*1560*18-*19, e1*2001/116*0480*36-*37, e1*2007/46*1878*08-*09, Types: 204 K, R1ES, 204 X, R1EAMG  |
| Company recall code                                 | 9295001   |
| Production dates                                    | The affected vehicles were manufactured between 24 January and 25 May 2020.   |
| OECD Portal Category                                | 77000000 - Automotive   |
| Description   | Passenger car   |
| Country of origin                                   | Germany   |
| Alert submitted by                                  | Germany   |
| Counterfeit *                                       | NO  |
| Risk type   | Injuries  |
| Technical defect                                    | The left-hand side, rear seat-back lock does not comply with the specifications. This could lead to a failure of the seat-back locking system in the event of an accident, increasing the risk of injury. |
| Risk  |   |
| Measures adopted by notifying country               | Recall of the product from end users  |
| Products were found and measures were taken also in | Greece, Ireland, Slovenia   |
| Images  | No pictures are available   |