



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00464/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Dacia
Name	Duster
Type / number of model	Type-approval number: e2*2001/116*0323*48-*51, e2*2007/46*0013*16-*20, Type: SR
Company recall code	0D8D
Production dates	The affected vehicles were manufactured between 26 November 2018 and 29 October 2019.
OECD Portal Category	77000000 - Automotive
Description	Passenger car under Dacia recall code: 0D8D.
Country of origin	Romania
Alert submitted by	Germany
Counterfeit *	NO
Risk type	Injuries
Technical defect	The frame of the rear seat may not be sufficiently strong. As a result, it will not be able to hold the luggage in the boot in the event of an accident, increasing the risk of an injury. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Images	No pictures are available