



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00780/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	McLaren
Name	McLaren 570GT, McLaren 720s, McLaren Senna, McLaren GT
Type / number of model	McLaren 570GT: e11*2007/46*3432*01 to e11*2007/46*3432*12 , McLaren 720S: e11*2007/46*3432*04 to e11*2007/46*3432*12 e5*2007/46*1205*00 to e5*2007/46*1205*04 , McLaren GT: e5*2007/46*1205*02 to e5*2007/46*1205*04, McLaren Senna: e11*2007/46*3432*08 to e11
Company recall code	
Production dates	McLaren 570GT – 01/05/2016 to 15/03/2019 McLaren 720s – 07/10/2016 to 26/02/2020 McLaren Senna – 26/04/2016 to 14/12/2019 McLaren GT – 10/08/2019 to 13/03/2020
OECD Portal Category	77000000 - Automotive
Description	
Country of origin	United Kingdom
Alert submitted by	United Kingdom
Counterfeit *	NO
Risk type	Fire
Technical defect	The noise vibration and harshness foam pad (NVH foam pad) situated underneath the fuel tank can potentially retain corrosive moisture from the environment that can cause micro-porations in the fuel tank. Consequently, small quantities of fuel may leak, posing a risk to the following traffic. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Images	No pictures are available